Work Order ID	
Monday, April 26, 2010	11:13:57



Page 1

Item ID: Revision ID:	D4034-043			Accept				s	etup Star		
Item Name: Start Date: Required Date Reference:	Fwd Upper R 4/26/2010 : 4/30/2010	Start Qty: 6.00 Req'd Qty: 6.00			Cust Item l Customer:	D:			Sto	P 	
Approvals:		an: MF	Date: 10-4-26	Tooling: SPC (Y/N):		ate:		R	tun Star Sto		
Sequence ID/ Work Center I	D	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	vision Nbr									
D4034 100 Large Fab Large Fab	, A	Memo 1- Assembl	rod Batch: MI/332	0.00				Sy	10/03	/06	(6x)
,		2- Weld bu	shing in rib as per dwg 🗸								
QC Quality Control	1 / 6	QC9- Inspect visual per Memo	QSI004- Fusion Welds	0.00 0.00 ·			(G PD	10.05.	<u>70</u>	
120 QC Quality Control	; ;	QC5- Inspect part comp	leteness to step on W/O	0.00	lostoz			(He)		

Dart Aerospace L	td	L	ce	а	מ	S	ro	e	Α	rt	Da
------------------	----	---	----	---	---	---	----	---	---	----	----

									• •
W/O:			WORK ORDER CHANGES						
DATE	STEP	PR	PROCEDURE CHANGE By						
						- 1			
Part No	•	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A:	Date: _	
	R	esolution:	Dispositi	on:	_ QA: N/C C	losed:		Date:	·
NCR:		1	WORK ORI	DER NON-CONFORMA	ANCE (NCI	₹)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	cation Approval	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	& Secti	on C	Chief Eng	QC Inspector
							•		
		-							

Work Order ID 58142

Monday, April 26, 2010 11:13:57 AM



Page 2

Item ID:

D4034-043

Accept

Accept

Qty

Setup Start



Revision ID:

Item Name:

Fwd Upper Rib Assembly

Start Date:

4/26/2010

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Required Date: 4/30/2010

Process Plan: _____

Memo

Date: _____

Date: _____

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Draw

Rev.

Plan

Code

Date:

Run



Stop

Reject

Qty

Number Stamp

Reject

Sequence ID/ Work Center ID

130

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location:

0.00

0.00

Start

Stop



Insp.

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

Memo

0.00

0.00

10/05/10 JX

	•									
W/O:			W	ORK ORDER CHANG	BES	··				. •
DATE	STEP	PRO	OCEDURE CHA	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	:									¥÷
Part No.		040 #							_	
Partino		PAR #:								
	H.	esolution:							Date:	
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC Section A	Corrective Action Section Initial Action Description			Sign &	Verific		Approval	Approval
		Section A	Chief Eng	Chief Eng		Date	Section	on C	Chief Eng	QC Inspector
			·							
		·								

Work Order ID: 58142

Parent Item: D4034-043

Parent Item Name: Fwd Upper Rib Assembly

Comments:

IPP RevA: new issue DD 09.11.23 verified by:EC

per dwg revA 10.03.15 verified by:EC

IPP Rev:B as

Start Date: 4/26/2010

Required Date: 4/30/2010

Start Oty: 6.00

Required Otv: 6.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D4034-1		Manufactured	No			100	Each	0.0000	6.0000	358151	6	SY 10/05
D4034-5		Manufactured	No			100	Each	5.0000	6.0000	3 <u>58158</u>	6.	JJ 10/0
		160 14		<u>Warehous</u> <u>Locati</u>	_	<u>Loc (</u>	<u>Oty</u>	Loc Code				. The state of the
3		•		Main Ware WA	ehouse		5.					

D2327-3
1 5 M W 15 (W 10 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Spacer Bushing

D4021-7

Manufactured

58038

100

Each

31.0000


6.0000

:		Warehouse Location	Lo	oc Qtv	Loc Code	
		Main Warehouse				
		WA		31		
		57186		11		
		57790		20		
Manufactured	No		100	Each	0.0000	6.0000

B 58153 6 M19/05/05


Dart Aerosp	pace Ltd	ı
--------------------	----------	---

W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PF	PROCEDURE CHANGE							Approval QC Inspector
· · · · · · · · · · · · · · · · · · ·										
				·						
Part No	•	PAR #:	Fault Cat	egory:	_ NCR: Y	es N	o DQ	A:	Date:	I.
	Re	esolution:	Dispositi	on:	QA: N/C	Clos	sed:		Date <u>;</u>	
NCR:			WORK ORI	DER NON-CONFORM	ANCE (N	CR)	<u> </u>			
DATE	STEP	Description of NC	1	Corrective Action Section			Verific	ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		gn & ate	Secti	on C	Chief Eng	QC Inspector
		· •								
							i			
<u>.</u>										



Dart Aerospace	Ltd
----------------	-----


W/O:			WC	RK ORDER CHANG	GES			····		3		
DATE	STEP	PR	OCEDURE CHAI					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No		PAR #:	Fault Cate	gory:	NC	R: Yes	No DQ	A:	Date:			
	Resc	olution:	Disposition	Disposition: QA: N/C Closed					sed: Date:			
NCR:			WORK ORDE	R NON-CONFORM	ANCE	(NCF	R)					
DATE	STEP	Description of NC	Corrective Action Section B Initial Action Description			Sign 8			Approval			
		Section A	Chief Eng	Chief Eng		Date	Secti	ion C	Chief Eng	QC Inspector		
·										1		
							1					



Dart Aerospace Ltd


W/O:			WC	RK ORDER CHANG	GES				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No:		PAR #:	Fault Cateç	jory:	NCR: Yes	No DQ	4 :	Date:	
Resolution:			Disposition	QA: N/C C	QA: N/C Closed: Date:				
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	Initial	stion B Sign	Verific		Approvai	Approval	
		Section A	Chief Eng	Action Description Chief Eng	Date		on C	Chief Eng	QC Inspector



Dart Aerospace

W/O:			W	ORK ORDER CHANG	GES		70.5				
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Approval Chief Eng / Prod Mgr	eng / Approvar			
							· · · · · · · · · · · · · · · · · · ·				
	:										
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes No DQA:				_ Date:	Date:	
		esolution:									
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)		-11, -1,8-1,			
DATE	STEP	Description of NC	Corrective Action Section			\ Variti			Approval	Approval	
		Section A	Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector	
										•	
									·		



Dart /	Aeros	pace	Ltd
--------	-------	------	-----

W/O:			WO	RK ORDER CHANG	GES	***************************************		··································		
DATE	STEP	PR	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				· ·						
					. •					
						a programa de la companya de la comp				
Part No	:	PAR #:	Fault Categ	ory:	NC	R: Yes I	No DQA	\:	Date:	
Resolution:			Disposition	QA:	N/C Clo	sed:		Date: 🊓		
NCR:				R NON-CONFORM					· · · · · · · · · · · · · · · · · · ·	
DATE	STEP Description of NC		Corrective Action Section B			Verifica			Approval	Approval
· · · · · ·		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
1.5.1		·								
										-
							,			
				$x_{i}^{i,j}$						
, V.				1. 7.	-			1		
		,								